



No. 10 NASCAR Sprint Cup Series Team Issued a Written Warning For Rules Infraction at Daytona International Speedway

DAYTONA BEACH, Fla. (Feb. 25, 2015) — The No. 10 team that competes in the NASCAR Sprint Cup Series has been issued a Written Warning for a rules infraction discovered during opening day inspection Feb. 13 at Daytona International Speedway.

Written Warnings are outlined in **Section 12.5.3.1** in the 2015 NASCAR rule book. This warning is for violation of Sections:

12-1 - Actions detrimental to stock car racing

20.11.2.2.2.1.b – Unapproved left-side driver heat shield; the outer exterior exhaust heat shield panel must follow the horizontal surface plane of the left side floorboard forward section to the bottom edge of the left side toe board